

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

新案出願公開
—62362

(1984) 4 月 24 日

求

(全 1 頁)

製作所内
会社
丸の内 2 丁目 5
外 2 名

第 2 図は本考案
は第 2 図の A—
レト用の穴、3:

⑬ 日本国特許庁 (JP)

⑭ 実用新案出願公開

⑫ 公開実用新案公報 (U)

昭 59—64453

① Int. Cl.³
F 02 F 11/00
F 16 J 15/06

識別記号

庁内整理番号
7616—3G
7111—3J

④ 公開 昭和 59 年 (1984) 4 月 27 日

審査請求 有

(全 1 頁)

⑨ シリンダーヘッドガスケット

東京都板橋区栄町 11—1

⑩ 出 願 人 日本パッキング工業株式会社
東京都港区虎ノ門 1 丁目 5 番 9
号

⑪ 実 願 昭 57—160015
⑫ 出 願 昭 57 (1982) 10 月 22 日
⑬ 考 案 者 掛須秀行

⑭ 代 理 人 弁理士 齊藤晴男


⑮ 実用新案登録請求の範囲

図面の簡単な説明

一枚の金属板で構成される中芯の上下両面に、
予め定位置にシリンダーボア、油水孔等を穿設し
た柔軟シートを定着したことを特徴とするシリ
ンダーヘッドガスケット。

第 1 図は本考案の実施例の構成を示す縦断面図、
第 2 図は他の実施例の縦断面図である。
符号の説明、1…金属板、2…ビード、3…シ
リンダーボア、4…グロメット、5…シート、6
…油水孔、7…リング。

オ 1 図



オ 2 図

